



THE AFTERMARKET INDUSTRY'S CHOICE FOR HIGHEST QUALITY
ELECTRONICS IN ROTATING ELECTRICAL PRODUCTS

COM REGULATORS

M464

Protocol: BSS

OEM Regulator #s: BMW 760377601, Valeo 2609960, 595464

Alternator #s: BMW 12-31-4-595-890, 1231-4-595-891, 12-31-7-575-344, & more



M543

Protocol: BSS

OEM Regulator #s: Valeo 2543204, 2543231, 593877, 593983, 593984, 599102

Alternator #s: BMW 12-31-7-521-178, 12-31-7-524-972, 12-31-7-525-376, & more



M545

Protocol: BSS

OEM Regulator #s: Valeo 591901, 593796, 595200, 595265, 599101

Alternator #s: BMW 12-31-7-788-821, 12-31-7-789-981, 12-31-7-789-984, & more



M567

Protocol: BSS

OEM Regulator #s: Valeo 2543591, 2610181, 595318, 599149

Alternator #s: BMW 12-31-7-535-097, 12-31-7-535-098, 12-31-7-576-513, & more



M571

Protocol: BSS

OEM Regulator #s: Valeo 2543208, 2604774, 595252, 595253, 595379

Alternator #s: Bosch 0986084100, Lucas LRA03030, & more



M575

Protocol: BSS

OEM Regulator #s: BMW 851008801, Valeo 2609956, 2609959, 591800, & more

Alternator #s: BMW 12-31-7-516-490, 12-31-7-516-723, 12-31-7-516-724, & more



M586

Protocol: BSS

OEM Regulator #s: Valeo 595416

Alternator #s: Renault 8200634135, 8200654541, Valeo TG9B041, TG9B042, TG9B107



M600

Protocol: BSS

OEM Regulator #s: Audi, Volkswagen 059903803G, Valeo 2608220, & more

Alternator #s: Audi, Volkswagen 021-903-016, 021-903-016X, 03G-903-016A, & more




M646

Protocol: BSS

OEM Regulator #s: Valeo 593986

Alternator #s: BMW 12-31-7-521-136, 12-31-7-521-137, 12-31-7-521-138, 12-31-7-836-610, 12-31-7-837-691



M233**Protocol:** LIN**OEM Regulator #s:** Valeo 595332, 599211, 599233**Alternator #s:** Audi, Volkswagen 039-903-016G, 03H-903-023L, & more**M234****Protocol:** LIN**OEM Regulator #s:** Valeo 2543587, 595305, 599234**Alternator #s:** Audi, Volkswagen 03G903-016F, 03G-903-016FX, & more**M236****Protocol:** LIN**OEM Regulator #s:** Valeo 599236**Alternator #s:** Audi, Volkswagen 03H903-023J, 03H-903-023JX, 03L 903 024 L, 03L903023N, 03L903023NX, & more**M565****Protocol:** LIN**OEM Regulator #s:** Valeo 2604291, 2607436**Alternator #s:** Ford 1469714, 1685794, 1698214, 1703864, 1871861, 7G9N-10300-CA, 7G9N-10300-CC, & more**M568****Protocol:** LIN**OEM Regulator #s:** Valeo 2604289, 593948, 593975, 595385**Alternator #s:** Mercedes-Benz 266-154-06-02, 266-154-09-02, A266-154-06-02, A266-154-09-02, & more**M573****Protocol:** LIN**OEM Regulator #s:** Valeo 2542604, 2543279, 595243**Alternator #s:** Chrysler 04801250AA, 04801250AB, 04801250AC, & more**M573V1****Protocol:** LIN**OEM Regulator #s:** Valeo 2619624, 595325, 599317**Alternator #s:** Mercedes-Benz 646-154-11-02, A646-154-11-02, Valeo TG17C061**M576****Protocol:** LIN**OEM Regulator #s:** Valeo 2543298, 593970, 595393, 599182, 599194**Alternator #s:** Ford 1469714, 1506299, 1685794, 1698214, 1704769, & more**M583****Protocol:** LIN**OEM Regulator #s:** Valeo 599240**Alternator #s:** Citroen 5702J9, 5705KV, 9803049980, Peugeot 9664779680, 9678048880, 9678058680, & more**M584****Protocol:** LIN**OEM Regulator #s:** Valeo 2612671, 2621055**Alternator #s:** Ford 31266149, 31285659, 36012505, AV6N-10300-GB, AV6N-10300-GC, AV6N-10300-GD, & more**M591****Protocol:** LIN**OEM Regulator #s:** Valeo 595291, 599171, 599296**Alternator #s:** Chrysler 68022877AA, 68022877AB, & more**M601****Protocol:** LIN**OEM Regulator #s:** Valeo 595371, 599161, 599213, 599241**Alternator #s:** Lucas LRA03408, Mercedes-Benz 0131546802, 01315468020080, & more

M603

Protocol: LIN

OEM Regulator #s: Valeo 599119, 599340

Alternator #s: Audi, Volkswagen 03C903-023T, 03C-903-023TX, 03D-903-025M, 03D-903-025MX, 03H-903-023E, & more



M609

Protocol: LIN

OEM Regulator #s: Valeo 2618689

Alternator #s: Nissan, Infiniti 23100-4BA0A; Valeo TG12C152



M610

Protocol: LIN

OEM Regulator #s: Valeo 2610614, 599125

Alternator #s: Mercedes-Benz 000-906-79-00, A-000-906-79-000, A-014-154-33-02, Valeo 2611843, FG18S032, FG18S077



M620

Protocol: LIN

OEM Regulator #s: Valeo 2618060B, 599237

Alternator #s: Audi, Volkswagen 04L 903 017A, 059-903-018QX, 059903018Q, 059903018QX, 06E-903-018L, & more



M154

Protocol: BSS

OEM Regulator #s: Valeo 599154

Alternator #s: Citroen 5705JG, 9666998080, PSA Peugeot Citroen 9666997980



M173

Protocol: BSS

OEM Regulator #s: Valeo 599173

Alternator #s: Nissan Infiniti 23100-7033R, Renault 23100-4554R



M648

Protocol: BSS

OEM Regulator #s: BMW7603775-01, Valeo 2343535, 2543505, 2591579, & more

Alternator #s: BMW 12-31-7533-469, 12-31-7-560-988, 12-31-7-560-989, & more



M588

Protocol: LIN

OEM Regulator #s: Valeo Tech 2710101

Alternator #s: FG15T093



M594

Protocol: LIN

OEM Regulator #s: Valeo 599187

Alternator #s: Citroen 9678058480, Peugeot 5702-J4, 5705-KR, 9678049480, 9803750980



M595

Protocol: LIN

OEM Regulator #s: Valeo 599212

Alternator #s: BMW 12-31-7-823-343, 12-31-8-509-224, 12-31-8-509-225



M596

Protocol: LIN

OEM Regulator #s: Valeo 599228, Valeo Tech 2617928B, 2617928M

Alternator #s: Mercedes-Benz 014-154-14-02, 271-154-14-02, 639-150-02-50, & more



M636

Protocol: LIN

OEM Regulator #s: Mercedes-Benz A0041542806, Valeo 2618712, 599304

Alternator #s: BMW 12-31-7-519-721, 12-31-7-519-723, 12-31-7-521-135, & more



WAI Corporate - USA
3300 Corporate Way
Miramar, FL 33025

Toll Free: 1-800-877-3340

WAI Canada - Toronto
535 Millway Avenue, Unit 1
Vaughan, Ontario, Canada, L4K 3V4

Toll Free: 1-800-387-2807

WAI China - Shanghai
Building No. 36 | 215 De Bao Rd
Wai Gao Qiao Free Trade Zone
Pudong, Shanghai 200131
Peoples Republic of China

Phone: 86-21-50482700

M652


Protocol: LIN
OEM Regulator #s: Valeo 599271
Alternator #s: Nissan Infiniti 23100-08633R, 23100-4BE0B, 23100-8633R, Opel 12022452, 4407989, & more

**IN6363**

Protocol: LIN
OEM Regulator #s: Denso 126600-3970, GC83970
Alternator #s: Acura 31100-5X6-J01, 31100-5X6-J01RM, 31100-RX0-A01, & more

**IN6373**

Protocol: LIN
OEM Regulator #s: Denso 126600-4360, 4360
Alternator #s: Denso 104211-3290, 104211-3291, 104211-3293, 104211-3531, & more

**IN6370**

Protocol: LIN
OEM Regulator #s: Denso 126600-4110, 126600-4310
Alternator #s: 104210-2330, 104210-6540, 104210-6541

**IM404**

Protocol: LIN
OEM Regulator #s: Honda 31150-R1A-A01, Mitsubishi 667, 6671404J, 6673X12H
Alternator #s: Acura 31100-R1A-A01, 31100-R1A-A010M2, & more

**IM624**


Protocol: LIN
OEM Regulator #s: Honda 31150-5A2-A01, Mitsubishi 7009Z18P
Alternator #s: Honda 31100-5A2-A02, 31100-5A2-A02RM, 31100-5A2-AA000M2, 31100-5B0-Y02, 31100-5B0-Y02RM, & more

**IM629**


Protocol: LIN
OEM Regulator #s: Mitsubishi 6954Z09L, 6955420L
Alternator #s: Ford 1741221, CJ5T-10300-CB, CJ5Z-10346-C, Mitsubishi A002TX2581, A002TX2581ZC

**IM912**


Protocol: BSS
OEM Regulator #s: Mitsubishi 5805912C
Alternator #s: Citroen 5702J3, 5705KQ, V757595680, V75759568002, V758575080, V75857508001, & more

**IB262**

Protocol: BSS
OEM Regulator #s: BMW 12-31-7-505-922, 12-31-7-523-059, 12-31-7-540-656, & more
Alternator #s: BMW 12-31-7-505-897, 12-31-7-516-101, 12-31-7-516-723, & more

**IB321**


Protocol: BSS
OEM Regulator #s: Bosch F 00M 144 131, F 00M 144 185, F 00M 144 188, & more
Alternator #s: Bosch 0 124 325 139, 0 124 325 176, 0 124 325 186, & more

**IB5289**

Protocol: BSS
OEM Regulator #s: BMW 12 31 7 512 163, 12 31 7 523 065, 12 31 7 540 655, & more
Alternator #s: BMW 12 31 7 521 488, 12 31 7 521 489, 12-31-4-456-281, & more

**IB5290**

Protocol: BSS
OEM Regulator #s: Bosch F 00M 145 308, F 00M 145 322
Alternator #s: Bosch 0 124 525 063, Citroen 5705CA, 9646452480, 9649846780, & more



WAI Corporate - USA
 3300 Corporate Way
 Miramar, FL 33025

Toll Free: 1-800-877-3340

WAI Canada - Toronto
 535 Millway Avenue, Unit 1
 Vaughan, Ontario, Canada, L4K 3V4

Toll Free: 1-800-387-2807

WAI China - Shanghai
 Building No. 36 | 215 De Bao Rd
 Wai Gao Qiao Free Trade Zone
 Pudong, Shanghai 200131
 Peoples Republic of China

Phone: 86-21-50482700

IB5881

Protocol: BSS

OEM Regulator #s: BMW 12 31 7 540 657, 12 31 7 542 530, 7 540 657, & more

Alternator #s: BMW 12-31-4-487-081, 12-31-4-487-081, 12-31-7-542-529, & more



IB6024

Protocol: BSS

OEM Regulator #s: BMW 12-31-7-561-924, 12-31-7-561-939, & more

Alternator #s: BMW 12-31-7-542-351, 12-31-7-550-469, 12-31-7-550-968, & more




IB6066

Protocol: BSS

OEM Regulator #s: BMW 12-31-7-577-245, Bosch F 00M 346 061, F 00M 346 066

Alternator #s: BMW 12-31-7-575-650, 12-31-7-575-873, 12-31-7-576-550, & more



IB6135

Protocol: BSS

OEM Regulator #s: Bosch F 00M 346 135

Alternator #s: BMW 12-31-7-604-782, 12-31-7-613-445, Bosch 0 125 711 011, & more




IB6866

Protocol: BSS

OEM Regulator #s: Bosch F 00M 145 866

Alternator #s: BMW 12-31-7-794-970, 12-31-7-806-779, Bosch 0 124 525 126




IB5378

Protocol: LIN

OEM Regulator #s: Bosch F 00M 144 158, F 00M 145 310, F 00M 145 378, F 00M 145 852, F 00M 145 886, & more

Alternator #s: Bosch 0 124 415 040, 0 124 625 023; Chrysler 68011841AA, & more




IB5379

Protocol: LIN

OEM Regulator #s: Bosch F 00M 145 311, F 00M 145 379, F 00M A45 212

Alternator #s: Bosch 0 124 525 060, 0 124 525 061, 0 124 525 521, & more



IB6020

Protocol: LIN

OEM Regulator #s: Bosch F 00M 346 006, F 00M 346 020, F 00M 346 036, & more

Alternator #s: Bosch 0 120 000 025, 0 121 813 001, 0 121 813 002, & more




IB6037

Protocol: LIN

OEM Regulator #s: Bosch F 00M 346 008, F 00M 346 021, F 00M 346 037, & more

Alternator #s: Bosch 0 121 715 006, 0 121 715 007, 0 121 715 011, & more



IB6056

Protocol: LIN

OEM Regulator #s: Bosch F 00M 346 005, F 00M 346 019, F 00M 346 056, & more

Alternator #s: Bosch 0 120 000 003, 0 120 000 029, 0 121 615 005, & more



IB6067

Protocol: BSS

OEM Regulator #s: BMW7603775-01, Valeo 2343535, 2543505, 2591579, & more

Alternator #s: BMW 12-31-7533-469, 12-31-7-560-988, 12-31-7-560-989, & more



IB6150

Protocol: LIN

OEM Regulator #s: Denso 126600-4110, 126600-4310

Alternator #s: 104210-2330, 104210-6540, 104210-6541



WAI Corporate - USA
3300 Corporate Way
Miramar, FL 33025

Toll Free: 1-800-877-3340

WAI Canada - Toronto
535 Millway Avenue, Unit 1
Vaughan, Ontario, Canada, L4K 3V4

Toll Free: 1-800-387-2807

WAI China - Shanghai
Building No. 36 | 215 De Bao Rd
Wai Gao Qiao Free Trade Zone
Pudong, Shanghai 200131
Peoples Republic of China

Phone: 86-21-50482700


IB6165

Protocol: LIN
OEM Regulator #s: Denso 126600-3940
Alternator #s: 104210-3551



IB6197

Protocol: LIN
OEM Regulator #s: Audi, Volkswagen 06E 903 803 F, 07K-903-803, & more
Alternator #s: Audi, Volkswagen 03C 903-023S, 03C-903-023SX, & more




IB885

Protocol: LIN
OEM Regulator #s: Bosch F 00M 144 157, F 00M 145 309, F 00M 145 377, F 00M 145 699, F 00M 145 885, & more
Alternator #s: Bosch 0 124 525 054, 0 124 525 055, 0 124 525 161, & more




IB293

Protocol: BSS
OEM Regulator #s: Bosch F 00M 144 147, F 00M 145 272, F 00M 145 293, F 00M 145 367, F 00M 145 385, & more
Alternator #s: Bosch 0 124 515 088, 0 124 515 198, 0 124 615 022, & more




IB6132

Protocol: BSS
OEM Regulator #s: Bosch F 00M 144 108, F 00M 144 132, F 00M 144 156, & more
Alternator #s: Bosch 0 124 625 014, 0 124 625 015, 0 124 625 045, & more



IB678

Protocol: BSS
OEM Regulator #s: BMW 12 31 7 515 811, XX XX 7 515 811, Bosch F 00M 145 278, F 00M 145 678, F 00M A45 218
Alternator #s: BMW 12-31-7-519-721, 12-31-7-519-723, 12-31-7-521-135, & more




IB203

Protocol: BSS
OEM Regulator #s: Bosch F 00M 255 203
Alternator #s: BMW 12-31-7-507-741, 12-31-7-507-995, Bosch 0 122 0AA 090



IB827

Protocol: LIN
OEM Regulator #s: Bosch 0 272 220 827
Alternator #s: F 000 BL0 889, F 000 BL0 897, F 000 BL0 8A3, F 000 BL0 8A5, & more



IB840

Protocol: LIN
OEM Regulator #s: Bosch 0 272 220 810
Alternator #s: Dacai 23100-8386R, 23100-8593R, Nissan Infiniti 23100-3730R, 23100-4426R, Renault 23100-8593R, 23100-3730R

